


117-081, 2135a, WFW2135a, M12191



REPLACEMENT PARTS LIST CORDLESS WELDER MODEL 117-081

ITEM	DESCRIPTION	PART NUMBER
1.	CASE, BACK	312-359-000
2.	NEGATIVE CAP & HOLSTER	312-279-000
3.	CABLE, GROUND ASSEMBLY	238-491-666
4.	BATTERY, 12V 17AH (REQUIRES 2)	ES1217
5.	CIRCUIT BREAKER	246-416-666
6.	PCB ASSEMBLY	880-437-666
7.	KEY SWITCH	246-425-666
8.	KNOB	246-470-000
9.	TEST BUTTON	312-277-000
10.	CASE, FRONT	312-344-000
11.	MOTOR COVER	312-265-000
12.	GEAR MOTOR/DRIVE ASSY	880-382-666
13.	GUN ASSY	238-542-000
14.	MOLDED COVER W/ KNOB	312-261-666
15.	SPINDLE W/ HARDWARE	312-262-666
16.	CHARGER (DOMESTIC, NOT SHOWN)	141-338-000
	CHARGER (EU, NOT SHOWN)	141-339-000
	CHARGER (UK, NOT SHOWN)	141-339-001
17.	KEY (NOT SHOWN)	312-301-000
18.	CONTACT TIPS (6 EA, NOT SHOWN)	4310X
19.	NOZZLE (NOT SHOWN)	334-203-000

SERVICING SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL.

FORM NO. 812-684-000

REV. A